



Seating Upholstery Alliance Program

Ultrafabrics Customer Service 877.309.6648 or icustomerservice@ultrafabricsinc.com

Order memo samples through Ultrafabrics Customer Service, Alliance website page, or www.ultrafabricsinc.com

All patterns not listed must be ordered as COM

This document is considered the most up-to-date listing of Ultrafabrics graded-in patterns

Even though we try to keep this document as accurate as possible, the supplier may change contents, finishes, etc...without our knowledge. Customer needs to confirm that the information on this listing matches the content information from the Alliance partner.

Pattern	Grade	Application Guidelines	Deletions	Contents	Finish	Backing	Are Flame Retardants Added	TB133 Status
Brisa® Original	E	None	03.22: 1359, 3866 12.21: 2523, 3275 01.21: 3234, 8203, 9374 01.20: 9310, 3233	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Brisa® Original Outdoor	K - Grade change to H April 18, 2022	None	02.22: 4435, 8214 01.20: 3160, 3823	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Brisa® Distressed	F	None	11.20: 4512	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Brisa® Distressed Outdoor	K - Grade change to H April 18, 2022	None	03.22: 3790 01.20: 3970 05.19: 3978	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Brisa® Fresco	G	None	12.20: 1342, 2565, 2570, 8210, 9390 01.20: 1341, 4445, 5265, 6585, 7313, 8211	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Brisa® Mokume	J	None	3.22: 2586, 3255 12.21: 2584, 2585, 3252	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	TB133 Burn Test Required
Brisa® Spectra	I	None		100% Polycarbonate Polyurethane	100% Polycarbonate Polyurethane Surface	65% Polyester, 35% Rayon Backing	No	TB133 Burn Test Required
Uf Select Impasto	D - Gr change to B May 16	None		PU 51%, Backing 49% +/- 5%	None	65% Polyester , 35% Cotton	No	TB133 Burn Test Required

Pattern	Grade	Application Guidelines	Deletions	Contents	Finish	Backing	Are Flame Retardants Added	TB133 Status
Uf Select Lino	D - Gr change to B May 16	None		PU 51%, Backing 49% +/- 5%	None	65% Polyester , 35% Cotton	No	TB133 Burn Test Required
Uf Select Montage	D - Gr change to B May 16	None		PU 51%, Backing 49% +/- 5%	None	65% Polyester , 35% Cotton	No	TB133 Burn Test Required
Ultraleather® Original	E	None	03.22: 1334, 6588, 8219 01.21: 7213, 9380 03.18: 3458, 3491, 4262, 5243, 8241	100% Polycarbonate Polyurethane	None	100% Reinforced Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Ultraleather® Cora Outdoor	I	None	3.22: deletion of remaining colors 12.21: 0002, 5920 01.21: 1332, 4390, 9315 01.20: 3250, 3506, 5220	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	TB133 Burn Test Required
Ultraleather® Fusion	J - Grade change to E April 18, 2022	None	01.20: 3699 05.19: 2539, 3590, 8226 02.19: 1310, 3849, 3872, 4470	100% Polycarbonate Polyurethane	None	82% Rayon, 18% Polyester	No	TB133 Burn Test Required
Ultraleather® Fusion Shimmer	J - Grade change to E April 18, 2023	None	05.19: 4480, 4483	100% Polycarbonate Polyurethane	None	82% Rayon, 18% Polyester	No	TB133 Burn Test Required
Ultraleather® Pearlized (Essence)	E	None	01.21: 4498, 5979, 6541 01.20: 3173	100% Polycarbonate Polyurethane	None	100% Reinforced Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Ultraleather® Pony	H	None	3.22: 3895 12.21: 3156, 3167, 3216	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	TB133 Burn Test Required
Ultraleather® Pro	F	None	3.22: 3214, 5649, 9336 12.21: 3353 06.21: 3353 01.20: 4453, 4478, 5216, 5241, 9395	100% Polycarbonate Polyurethane	None	100% Reinforced Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Ultraleather® Promessa®	F	None	3.22: 1396, 3148, 3195, 5263, 9371 12.21: 4515 06.21: 3462 01.20: 1398, 3139, 3140, 3143, 3224, 4514, 4516, 5848	100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Ultraleather® Promessa® Outdoor	J	None		100% Polycarbonate Polyurethane	None	65% Polyester, 35% Rayon	No	**Approved on many TB133 seating models; restricted on lounge models
Ultraleather® Reef Pro	G	None		100% Polycarbonate Polyurethane	Ink Resist	Polyester 65%, Rayon 35% (Twill Weave)	No	TB133 Burn Test Required
Ultraleather® Tottori	F	None		100% Polycarbonate Polyurethane	None	65% Polyester/35% Rayon	No	TB133 Burn Test Required
Ultraleather® Volar Bio	J	None		Proprietary Polycarbonate + Biobased Surface	None	65% Polyester / 35% Rayon	No	TB133 Burn Test Required

Pattern	Grade	Application Guidelines	Deletions	Contents	Finish	Backing	Are Flame Retardants Added	TB133 Status
Ultratech™ Cove	G	None	3.22: deleted remaining colors 12.21: 5943, 3301, 5247, 5970	100% Polycarbonate Polyurethane	65% Polyester, 35% Rayon	65% Polyester, 35% Rayon	No	TB133 Burn Test Required
Ultratech™ Dwell	F	None	01.20: 2524, 3217, 4430 05.19: 6586	100% Polycarbonate Polyurethane	None	100% Reinforced Rayon	No	TB133 Burn Test Required
Ultratech™ Eco Tech	F	None	02.22: 4431,4531 01.20: 1369, 2519, 8202	100% Polycarbonate Polyurethane	None	82% Rayon, 18% Polyester Backing	No	TB133 Burn Test Required
Ultratech™ Helix	G	None	3.22: deletion of remaining colors 12.21: 5949, 0020 01.21: 4391, 9382	100% Polycarbonate Polyurethane	65% Polyester, 35% Rayon	65% Polyester, 35% Rayon	No	TB133 Burn Test Required
Ultratech™ Wired	G	None		100% Polycarbonate Polyurethane	65% Polyester, 35% Rayon	65% Polyester, 35% Rayon	No	TB133 Burn Test Required